How to create a good SES with less mistakes?

JORGE SÁNCHEZ GALÁN - ES





TALK CONTENTS

- → WHAT'S NEW?
- → SES COMMON MISTAKES
 - ◆ GENERAL
 - **♦ TUBULAR CHASSIS**
 - ♦ MONOCOQUE CHASSIS
- → ASES COMMON MISTAKES
- → SES/ASES DURING TECH.
 INSPECTION
- → DOUBTS & QUESTIONS





CHANGES FOR 2025

Dropped requirement for significant changes (A2.2.2) - **New manufactured chassis is required.**

AIP is now considered **primary structure** (*T1.1.12*).

Added fire retardant standard for foams: UL94HF-1 and UL94 VTM-0 (77.2.1).

Introduced malus for low property steels (*T3.2.4*) - Use the standard values or the ones present in the datasheet, whichever is lower.

Limited usage of alternative **proof of equivalence per actual EI** (*T3.4.1*) - Only applicable if the flat panel EI exceeds **60% of the minimum requirements** .



CHANGES FOR 2025

Relaxed requirement for asymmetrical laminates (T3.4.4) - Thk \geq 40% thicker skin or 1 mm, whichever is lower.

New requirement for asymmetrical laminates shear tests (T3.5.10) - The thinner skin must face the punch.

Extended requirements within the **SE3D** (*T3.6.3*).

Stricter requirement on harness attachment brackets/tabs (74.5.5) - All except steel must be physically tested.

Enforced backing plate also in AIP to FBH attachment and bolted panels or plates of the primary structure (*T3.15.6*).

Introduced **physical testing requirement for usage of blind inserts** in primary structure attachments (*T3.15.7*).



CHANGES FOR 2025

New document - ASES (*T3.6.1, EV5.5.4*).

Changed minimum wall height (*EV5.5.7*) - Accumulator internal walls must extend upwards until the lid.

Defined minimum number of attachment points (2) for TSAC mounting (EV5.5.13).

Removed redundant force (20 kN at any direction) requirement for TSAC mounting points (EV5.5.13).


TSAC walls holes can extend to the edge of a wall (EV5.5.74)



General

Missing images and required dimensions on tabs:

- → Chassis pics
- → FBH, FHB, FBHS, AIP...
- → Firewall, SHB.






General

Missing datasheets and/or proof of purchase for relevant materials.

- Steel.
- FRP.
- Resins and adhesives.
- Foams and other cores.






General

Strength justification by means of FEM images without proper model description.

TIP! Try to use analytical calculations whenever possible.






General

SES and SE3D do not reflect the same version of the car.


Different tabs of SES reflect different versions of the car.





General


Poor visibility of values in CAD captures and other required photographies.





General

Wrong harness distance on tab *T5.5 Shoulder Harness Bar.*






General

Lack of clear information on firewall lay-up and assembly to the structure.

Example of good firewall description






Tubular chassis

Incorrect tube count → Typically on FBH, FBHS and (EV only)
ACPS/TSPS Rear


FBH - ACPS/TSPS Rear Example




N° of tubes = 2.5



FBHS Examples








N° of tubes = 4



Tubular chassis

Wrong structure triangulation : FBHS, SIS and (EV only) ACPS/TSPS side.





Tubular chassis

Lack of test for strength on welded condition when using alloyed steels.






Monocoque chassis

Wrong panel height calculation, typically on MHBS, FHB, FBHS.


Important! Always consider the most restrictive measure in case of holes or cuts in the panel.

MHBS Panel height calculation






FHB panel height



FBHS panel height






Monocoque chassis

Incorrect calculation of skins inertia for the geometrical probe of panel strength.

Example of FHB panel strength equivalence





Monocoque chassis

Incorrect election of peak values or reference points for gradient calculation in alternative material test results (3 point bending and shear tests).

Reference points don't match with test graph



Figure 2: Load Deflection Curve for vertical Side impact structure


Enter values for minimum and maximum load/deflection in linear-elastic region.

radient must be >= that of two baseline steel t $x_1(mm)$ 3,344 $y_1(N)$ 4907,813

Gradient (N/mm) 3204



Peak identification in shear tests





2025 SES RELEVANT CHANGE

Change in rig compliance consideration

Rig compliance minimum value increased to 85% (previously 75%).


Relation between rig compliance and gradient calculation removed.



Monocoque chassis

Lack of calculation to justify that the laminated FH complies with *T3.9.5* and *T3.9.6*

Example of good calculations






Lack of datasheets and/or proof of purchase for relevant materials:

- FRP
- Adhesives and resins
- Aluminum
- Foams, cores, insulation materials...


Missing material fire rating on datasheet.





FEM analysis as part of accumulation mechanical strength justification without proper model explanation.


Missing calculations for some of the components of the accumulator structure → All accumulator structure components must withstand the accelerations marked in *T9.3.1*.



FEM analysis as justification without detailed model explanation



Analytical calculations for different accumulator walls





Poor visibility of the required dimensions and values in the attached images.

Incomplete information in the fire retardant material test report (if applicable).

Lack of strength calculations for bolted joints between accumulator internal components and accumulator attachments.

Example of good fire retardant material test report





SES/ASES DURING TECH. INSPECTION

What to bring?

All tests samples correctly marked for alternative materials on accumulator and primary structure.

Physically tested IA assembly, including representative test fixture (if applicable).

Physical or digital copy of SES (mechanical) and ASES (accumulator).





SES/ASES DURING TECH. INSPECTION

Common problems

Firewall doesn't match with SES design → Presence of holes and gaps.

IA height above 350mm due to car setup.

Cockpit opening and cockpit cross section smaller than required by rules.





SES/ASES DURING TECH. INSPECTION

Common problems

Lack of inspection holes on Front Hoop, Main Hoop and Main Hoop Bracing.

Difficult to check primary structure mounting points

Presence of manufacturing defects: delaminations, improper welds, etc.





DOUBTS & QUESTIONS







SLIDE TITLE







SUBTITLE (IF NEEDED)

TEXT BLOCK 1

LINE 1

LINE 2

LINE 3

LINE 4

LINE 5

LINE 6

LINE 7

LINE 8



SLIDE TITLE

SUBTITLE (IF NEEDED)

TEXT BLOCK 1

LINE 1

LINE 2

LINE 3

LINE 4

TEXT BLOCK 2

LINE 1

LINE 2

LINE 3

LINE 4

