

Team Penalty

From: FSPT Team

Date: 07/09/2024

To: UJI Motorsports - 214

Time: 23:00

Infringed rule(s)

T5.4.3	<i>In side view, the lap belt must be capable of pivoting freely by using either a shouldered bolt or an eye bolt attachment.</i>
--------	---

Team's action

The left lap belt metal carabiner was damaged in a way that did not allow free pivoting.

Penalty applied

IN12.1.4 Group A violation of the rules without advantage for the team. A penalty of 30 seconds shall be applied to the overall endurance time.

Responsible

António Bento
Chief Scrutineer

Protest deadline: 11:59 08/09/2024