

Team Penalty

From: FSPT Team

Date: 07/09/2024

To: Team Bath Racing Electric - 67

Time: 23:00

Infringed rule(s)

T7.2.4	<i>Any cooling or lubrication system must be sealed to prevent leakage.</i>
--------	---

Team's action

One streak of small grease droplets along the undertray and rear structure of the car was visible in alignment with both tripod sleeves.

Penalty applied

IN12.1.4 Group A violation of the rules without advantage for the team. A penalty of 30 seconds shall be applied to the overall endurance time.

Responsible

António Bento
Chief Scrutineer

Protest deadline: 11:59 08/09/2024